

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 10021176 Main Street: BILLINGSLEY RD Cross Street: N/A Location: NW Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 1F951D595615 Ramp Type: PerpDiag Severity Score: 13.75

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance



**BILLINGSLEY RD** Street 1 Name Stop Condition-Street 2 None **ENTRANCE** Street 2 Name Stop Condition-Street 1 StopSign

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.2, R304.5.3

N/A Total Cost: 3200.00

Compliance Description Data Compliance Description Data No Ramp Slope (%) N/A Ramp Length (in) 24.5 10.1 No Ramp XSlope (%) Yes Ramp Width (in) 48.0 3.6 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A **DWS Provided?** N/A Landing Length (in) Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To S X Walk 2 Direction To E N/A X Walk 2 Width (in) X Walk 1 Width (in) N/A X Walk 1 Slope (%) 6.3 X Walk 2 Slope (%) 4.0 X Walk 1 X Slope (%) 2.5 X Walk 2 X Slope (%) 2.8 N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 0.5 N/A Clear Space? N/A N/A Road X Slope (%) 7.1 Clear Space to XWalk (in) N/A N/A Any Obstructions? N/A Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good





