

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

| Intersection ID: 51635 | Main Street: NATIONS_FORD_RD | | | Cross Street: TOCCOA_FALLS_DR | | | | Location: | NW |
|---|------------------------------|------------------------------|---------|--|-----------------------|------|-----|-----------------------------|------|
| ADA ID: 1F9D11F6257E | 7E Ramp Type: PerpDiag | | | itial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 8.75 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| | | Possible Solutions: | | | | | | ompliance Description Data | |
| | | Remove & Replace Curb Ram | n With | N/A | Ramp Length (in) | 80.0 | | Ramp Slope (%) | 5.2 |
| | | Two New Directional Ramps of | • | No | Ramp Width (in) | 45.5 | | Ramp XSlope (%) | 0.6 |
| | | Equivalent. | 51 | N/A | Flare Type LT | N/A | | Flare Type RT | N/A |
| | | | | N/A | Flare Slope LT (%) | | N/A | Flare Slope RT (%) | N/A |
| | | | | N/A | Flare Traversable LT? | N/A | | Flare Traversable RT? | N/A |
| | | | | N/A | Landing Length (in) | N/A | | DWS Provided? | N/A |
| | | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| A A A A A A A A A A A A A A A A A A A | | N/A | | N/A | Landing Slope (%) | | N/A | DWS Length (in) | N/A |
| TOCCOA FALLS DR | | N/A | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | | | | N/A | Landing Curb? (Y/N) | N/A | | DWS Offset (in) | N/A |
| the second the second | | | | N/A | Shared Landing? | N/A | | BWG Onset (m) | 10/4 |
| A CONTRACT OF | | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | | - | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | | Not Found, R304.5.1 | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | | | | N/A | X Walk 1 Direction | To S | N/A | X Walk 2 Direction | To E |
| | | | | N1/A | | | | | |
| | | | | N/A | X Walk 1 Width (in) | | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name | TOCCOA FALLS DR | | | | X Walk 1 Slope (%) | 3.6 | | X Walk 2 Slope (%) | 5.0 |
| Stop Condition-Street 2 | StopSign | | | | X Walk 1 X Slope (%) | 4.7 | | X Walk 2 X Slope (%) | 4.8 |
| Street 2 Name | NATIONS FORD RD | | | N/A | Ramp inside XWalk1? | | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | None | | | | Road Slope (%) | 0.4 | N/A | Clear Space? | N/A |
| | | | | | Road X Slope (%) | 7.1 | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: \$ | 3200.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | N/A | | | N/A |

