

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 25815Main Street: REA_RDCross Street: PINEVILLE-MATTHEWS_RDLocation:SEADA ID: 1FD100844F1BRamp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score:10

Codes/Mitigation Info/Possible Solution



Street 1 Name REA RD
Stop Condition-Street 2 Signal
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:				
Remove & Replace Entire Ramp.				
	ı			
Surveyor Notes:				
N/A	ı			
	ı			
	ı			
PROW/ADA:				
Not Found, R304.5.1, R304.5.3	,			
	,			
	ı			
	ı			





Total Cost:



1850.00

Field Measurements/Component Compliance								
Compl	liance Description	Data	Comp	liance Description	Data			
N/A	Ramp Length (in)	67.0	Yes	Ramp Slope (%)	7.4			
No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	3.8			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A			
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A			
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A			
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A			
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A			
	X Walk 1 Direction	To W		X Walk 2 Direction	N/A			
N/A	X Walk 1 Width (in)	108.0	N/A	X Walk 2 Width (in)	N/A			
	X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	N/A			
	X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	N/A			
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A			
	Road Slope (%)	N/A	N/A	Clear Space?	N/A			
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A			
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm Grate/Utility Type				
		N/A			N/A			
			Yes	Surface Condition? (G/P)	Good			
CONTRACTOR OF THE PARTY	NUMBER OF STREET							