


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: N/A	Main Street: AGNEW_DR	Cross Street: COWGILL_LN	Location: SE
ADA ID: 1FF0629CEF72	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	
Severity Score: 21.25			

	Possible Solutions:						
	Remove & Replace Entire Ramp.						
	Surveyor Notes:						
	N/A						
	PROW/ADA:						
	Not Found, R304.5.1, R304.2.2						
				Compliance	Description	Data	Compliance
				Description			Description
				Data			Data
Street 1 Name	AGNEW DR				N/A	Ramp Length (in)	97.0
Stop Condition-Street 2	None				No	Ramp Width (in)	47.5
Street 2 Name	N/A				N/A	Flare Type LT	N/A
Stop Condition-Street 1	N/A				N/A	Flare Slope LT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A
				N/A	Flare Slope RT (%)	N/A	N/A
				N/A	Flare Traversable RT?	N/A	N/A
				N/A	DWS Provided?	N/A	N/A
				N/A	DWS Contrast?	N/A	N/A
				N/A	DWS Length (in)	N/A	N/A
				N/A	DWS Full Width?	N/A	N/A
				N/A	DWS Offset (in)	N/A	N/A
				N/A	Shared Landing?	N/A	
				N/A	Gutter Ponding?	N/A	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A
				N/A	Painted X Walk1?	No	N/A
					X Walk 1 Direction	To SW	X Walk 2 Direction
				N/A	X Walk 1 Width (in)	N/A	N/A
					X Walk 1 Slope (%)	3.5	X Walk 2 Width (in)
					X Walk 1 X Slope (%)	1.4	X Walk 2 Slope (%)
				N/A	Ramp inside XWalk1?	N/A	N/A
					Ramp inside XWalk2?	N/A	N/A
					Road Slope (%)	N/A	N/A
					Clear Space?	N/A	N/A
					Clear Space to XWalk (in)	N/A	N/A
				N/A	Any Obstructions?	N/A	N/A
					Obstruction Type		Storm Grate/Utility Hazard?
							Storm Grate/Utility Type
				N/A			N/A
				Yes	Surface Condition? (G/P)		Good

Total Cost: \$ 1850.00

