

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13639 Main Street: BRIAR_CREEK_RD Cross Street: CENTRAL_AV Location: NE **Overall Compliance: No Severity Score: ADA ID: 1FF59DE66869** Ramp Type: Perp Initial Pass/Fail: Fail 22.5

Codes/Mitigation Info/Possible Solution



Street 1 Name	CENTRAL AV
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

1 Ossible Solution	
Possible Solutions:	Co
Remove & Replace Entire Ramp. Restripe Crosswalk.	
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.5.1, R304.2.2,	N/A
R304.5.3	N/A
	N/A
	N/A

Total Cost:	\$ 2050.00

Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	liance	Description	Data	
N/A	Ramp Length (in)	48.5	No	Ramp	Slope (%)	9.9	
No	Ramp Width (in)	47.0	No	Ramp	XSlope (%)	3.9	
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A	
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A	
N/A	Painted X Walk1?	Yes	N/A	Paint	ed X Walk2?	N/A	
	X Walk 1 Direction	To S		X Wa	lk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	100.0	N/A	X Wa	ılk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	3.5		X Wa	lk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	2.8		X Wa	lk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	No	N/A	Ram	o inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A	
	Obstruction Type			Storn	n Grate/Utility Type		
		N/A				N/A	
			Yes	Surfa	ce Condition? (G/P)	Good	





