## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12028	Main Str	reet: ROBINSON_CHURCH_RD	Cross Street: WILLOW_GATE_LN					Location:	SE
ADA ID: 202B6D97E158 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	1.3 2,0	Possible Solutions:		Comp	liance Description	Data	Comp	liance Description	Data
The states	A CALL MAL	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	69.0	No	Ramp Slope (%)	9.2
				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.0
	The man	•		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
and the second	34 1 . O (16)			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	· · · · · · · ·			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
ROBINSON_CHURCH	LRD			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	ALC STORES	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
ter	Contraction of the second	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	and the second se			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Sec.	the light of the second			N/A	Shared Landing?	N/A			
OT FE	Pro to	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Still 2	··· ···	Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	All A.			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To W		X Walk 2 Direction	N/A
192	and the second second			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	WILLOW GATE LN				X Walk 1 Slope (%)	4.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

