

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 44723	Main Street: PROSPERITY_CHURCH_RD			Cross Street: JOHNSTON_OEHLER_RD				Location:	SE	
ADA ID: 2064B8F7F5A8	Ramp Type: IslandPerp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description Data Complia			liance Description	Data		
	-1-	Remove & Replace Entire Ramp		N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	8.9	
STATISTICS DI	1440			Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	2.4	
	1 H MAY DE	4		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
a a a a a a a a a a a a a a a a a a a				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
E B			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
6 12	201			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	XX			N/A	Shared Landing?	N/A				
11 13 14	1) Seal	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	X X			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
				X Walk 1 Direction	To N		X Walk 2 Direction	N/A		
18 2 2 3 1 1 V			N/A	X Walk 1 Width (in)	106.0	N/A	X Walk 2 Width (in)	N/A		
Street 1 Name JOHNSTON OEHLER RD					X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A		Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3400.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

