

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 7830	Main Street: ABELWOOD_RD				Cross Street: ENGLISH_DR				Location: SE		
ADA ID: 213446A80EBD	Ramp Ty	Ramp Type: Combination1			Initial Pass/Fail: Fail Overall Compli			nce: No Severity Score: 37.5		37.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	Cur .	Possible Solutions:			Compliance Description		Data Compliance Description			Data	
Carlos and the second	ALT PLANE	Remove & Replace En	Entire Ramp.		N/A	Ramp Length LT (in)	46.0	N/A	Ramp Length RT (in)	38.0	
		•		•	Yes	Ramp Width LT (in)	56.0	Yes	Ramp Width RT (in)	56.0	
					Yes	Ramp Slope LT (%)	6.4	No	Ramp Slope RT (%)	11.5	
	A 8 804				No	Ramp XSlope LT (%)	4.4	Yes	Ramp XSlope RT (%)	0.2	
					N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	5.7	
TOOD RU	Call to Str.				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	9.1	
AEEUVO	1315	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
the second second		N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
Y	1. 1. S. S.	Not Found, R304.5.3, F	R304.3.2		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
Autor Autor C I I I	A DA	, ,			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
A CONTRACTOR AND	A Share and				N/A	Shared Landing?	N/A				
	Mar Mill	And the second se			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	BELWOOD RD				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To N		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	7.9		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					IN LL			N/A	Any Obstruction?	N/A	
									Obstruction Type		
										N/A	
					-				Storm Grato/Utility Hazard?		

- N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good
 - Surface Condition? (G/P)GoodCurb Slope (%)14.9





