

## Access Compliance Report Public Rights-of-Way (Curb Ramps)




Intersection ID: 48985 Main Street: AVONCLIFF\_DR Cross Street: KINGSDOWN\_AV Location: SW

ADA ID: 21374AFDA802 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 33.75

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

AVONCLIFF DR StopSign KINGSDOWN AV None Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Field Measurements/Component Compliance						
Compliance Description		Data	Comp	oliance Description	Data	
1	N/A	Ramp Length (in)	69.0	Yes	Ramp Slope (%)	7.2
1	No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	7.4
N	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
1	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
1	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
1	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
1	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
1	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
1	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
1	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
1	N/A	Shared Landing?	N/A			
1	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
1	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	То Е		X Walk 2 Direction	To N
1	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	4.8		X Walk 2 Slope (%)	3.4
		X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	6.6
1	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	5.4	N/A	Clear Space?	N/A
		Road X Slope (%)	2.9	N/A	Clear Space to XWalk (in)	N/A
1	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type			Storm Grate/Utility Type	
			N/A			N/A
				Yes	Surface Condition? (G/P)	Good





