


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 16365	Main Street: QUEENS_RD	Cross Street: SHERWOOD_AV	Location: NE
ADA ID: 216DAB1C8803	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	
Severity Score: 13.75			

	Possible Solutions:						
	Remove & Replace Entire Ramp.						
<p>Surveyor Notes:</p> <p>N/A</p>	<p>PROW/ADA:</p> <p>R304.2.2, R304.5.3</p>	Compliance	Description	Data	Compliance	Description	Data
		N/A	Ramp Length (in)	78.0	N/A	Grade Break?	N/A
<p>Street 1 Name</p> <p>SHERWOOD AV</p>	<p>Stop Condition-Street 1</p> <p>StopSign</p>	Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0
		No	Ramp Slope (%)	9.1	N/A	Grade Break XSlope (%)	0.0
<p>Street 2 Name</p> <p>N/A</p>	<p>Stop Condition-Street 2</p> <p>N/A</p>	No	Ramp XSlope (%)	2.4	N/A	Flare Type RT	N/A
		N/A	Flare Type LT	N/A	N/A	Flare Slope RT (%)	0.0
<p>Total Cost:</p> <p>\$ 1600.00</p>		N/A	Flare Slope LT (%)	N/A	N/A	Flare Traversable RT?	N/A
		N/A	Flare Traversable LT?	N/A	N/A	DWS Provided?	N/A
		N/A	Landing Length (in)	0.0	N/A	DWS Contrast?	N/A
		N/A	Landing Width (in)	0.0	N/A	DWS Length (in)	N/A
		N/A	Landing Slope (%)	0.0	N/A	DWS Full Width?	N/A
		N/A	Landing X Slope (%)	0.0	N/A	DWS Offset LT (in)	N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset RT (in)	N/A
		N/A	Shared Landing?	N/A	N/A	Gutter Slope (%)	N/A
		N/A	Gutter Ponding?	0.0	N/A	Gutter X Slope (%)	N/A
		N/A	Gutter Lip Ht (in)	0.0	N/A	Road Slope (%)	0.0
		N/A	Painted X Walk1?	No	N/A	Road X Slope (%)	4.9
		N/A	X Walk 1 Direction	To S	N/A	Clear Space?	N/A
		N/A	X Walk 1 Width (in)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	X Walk 1 Slope (%)	0.0	N/A	Storm Grate/Utility Hazard?	N/A
		N/A	X Walk 1 X Slope (%)	4.9	N/A	Storm Grate/Utility Type	N/A
		N/A	Ramp inside XWalk1?	N/A	N/A	Surface Condition? (G/P)	Good
		N/A	Any Obstructions?	N/A	N/A	Curb Slope (%)	10.4
		N/A	Obstruction Type		N/A		

