

	Possible Solutions:		Remove & Replace Entire Ramp.	
	Surveyor Notes:		LT RP < 5%	
	PROW/ADA:		R304.5.3, R304.3.2	
	Total Cost:		\$ 1600.00	
Street 1 Name	PROVIDENCE RD		Street 2 Name	N/A
Stop Condition-Street 1	Signal		Stop Condition-Street 2	N/A

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	60.5	N/A	Ramp Length RT (in)	61.0
Yes	Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	59.0
Yes	Ramp Slope LT (%)	1.2	No	Ramp Slope RT (%)	12.6
No	Ramp XSlope LT (%)	2.7	Yes	Ramp XSlope RT (%)	2.0
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Ponding?	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Painted X Walk2?	N/A
N/A	Painted X Walk1?	Yes	N/A	X Walk 2 Direction	N/A
	X Walk 1 Direction	To E	N/A	X Walk 2 Width (in)	N/A
N/A	X Walk 1 Width (in)	105.0		X Walk 2 Slope (%)	N/A
	X Walk 1 Slope (%)	1.6		X Walk 2 X Slope (%)	N/A
	X Walk 1 X Slope (%)	2.6	N/A	Ramp inside XWalk2?	N/A
N/A	Ramp inside XWalk1?	Yes	N/A	Clear Space?	N/A
	Road Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
	Road X Slope (%)	N/A	N/A	Storm Grate/Utility Hazard?	N/A
N/A	Any Obstructions?	N/A		Storm Grate/Utility Type	
	Obstruction Type				
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	18.2

