

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 13734	Main Street: S. TRYON ST			Street	W KINGSTON AV	Location:	w			
	Main Street: S_TRYON_ST			Cross Street: W_KINGSTON_AV						
ADA ID: 218F95126B01	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	Est	Possible Solutions:	Compliance Description D			Data	ata Compliance Description		Data	
		Remove & Replace Entire Ramp		N/A	Ramp Length (in)	61.0	No	Ramp Slope (%)	8.9	
For marks 1	E BEB T			No	Ramp Width (in)	42.0	Yes	Ramp XSlope (%)	0.9	
	1. 1			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
Sector In the	N.			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
MINGST				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
the second	AV &			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
X PALL	1 1	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
Karley Det a		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
Lon	<u>k</u>			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
S Jus	A summit			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
AL A				N/A	Shared Landing?	N/A				
	The same strand	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	No. The	R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
1 Marie		,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
					X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	S TRYON ST				X Walk 1 Slope (%)	4.3		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

