


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                       |                         |                         |                        |                      |
|-----------------------|-------------------------|-------------------------|------------------------|----------------------|
| Intersection ID: 9891 | Main Street: RAPHAEL_PL | Cross Street: CARD_ST   | Location:              | N                    |
| ADA ID: 2238E3A3BF89  | Ramp Type: PerpDiag     | Initial Pass/Fail: Pass | Overall Compliance: No | Severity Score: 2.75 |

| Codes/Mitigation Info/Possible Solution  |  |   | Field Measurements/Component Compliance |                       |        |            |                             |       |
|--|--|---|---|-----------------------|--------|------------|-----------------------------|-------|
|  | Possible Solutions:  |   | Compliance                              | Description           | Data   | Compliance | Description                 | Data  |
|  | Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. |   | N/A                                     | Ramp Length (in)      | 91.0   | Yes        | Ramp Slope (%)              | 8.0   |
|  |  |   | Yes                                     | Ramp Width (in)       | 48.0   | No         | Ramp XSlope (%)             | 2.4   |
|  |  |   | N/A                                     | Flare Type LT         | Sloped | N/A        | Flare Type RT               | N/A   |
|  |  |   | N/A                                     | Flare Slope LT (%)    | 5.5    | No         | Flare Slope RT (%)          | 10.5  |
|  |  |   | N/A                                     | Flare Traversable LT? | Yes    | N/A        | Flare Traversable RT?       | Yes   |
|  |  |   | No                                      | Landing Length (in)   | 39.0   | Yes        | DWS Provided?               | Yes   |
|  |  |   | Yes                                     | Landing Width (in)    | 48.0   | Yes        | DWS Contrast?               | Yes   |
|  |  |   | No                                      | Landing Slope (%)     | 4.2    | Yes        | DWS Length (in)             | 25.5  |
|  |  |   | Yes                                     | Landing X Slope (%)   | 0.1    | Yes        | DWS Full Width?             | Yes   |
| Surveyor Notes:  |  | N/A   | N/A                                     | Landing Curb? (Y/N)   | No     | No         | DWS Offset (in)             | 5.0   |
| PROW/ADA:  |  | Not Found, R304.5.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.2.3, R305.2 | N/A                                     | Shared Landing?       | No     |            |                             |       |
|  |  |   | Yes                                     | Gutter Ponding?       | No     | Yes        | Gutter Slope (%)            | 4.1   |
|  |  |   | Yes                                     | Gutter Lip Ht (in)    | 0.0    | Yes        | Gutter X Slope (%)          | 1.6   |
|  |  |   | N/A                                     | Painted X Walk1?      | No     | N/A        | Painted X Walk2?            | No    |
|  |  |   |   | X Walk 1 Direction    | To SW  |            | X Walk 2 Direction          | To SE |
|  |  |   | N/A                                     | X Walk 1 Width (in)   | N/A    | N/A        | X Walk 2 Width (in)         | N/A   |
|  |  |   |   | X Walk 1 Slope (%)    | 4.7    |            | X Walk 2 Slope (%)          | 1.9   |
|  |  |   |   | X Walk 1 X Slope (%)  | 1.5    |            | X Walk 2 X Slope (%)        | 2.7   |
|  |  |   | N/A                                     | Ramp inside XWalk1?   | N/A    | N/A        | Ramp inside XWalk2?         | N/A   |
|  |  |   |   | Road Slope (%)        | 1.6    | N/A        | Clear Space?                | Yes   |
|  |  |   |   | Road X Slope (%)      | 6.1    | N/A        | Clear Space to XWalk (in)   | N/A   |
|  |  |   | Yes                                     | Any Obstructions?     | No     | Yes        | Storm Grate/Utility Hazard? | No    |
|  |  |   |   | Obstruction Type      |        |            | Storm Grate/Utility Type    |       |
|  |  |   |   |                       | N/A    |            |                             | N/A   |
|  |  |   |   |                       |        | Yes        | Surface Condition? (G/P)    | Good  |
| Street 1 Name  |  | RAPHEAL PL  |   |                       |        |            |                             |       |
| Stop Condition-Street 2  |  | StopSign  |   |                       |        |            |                             |       |
| Street 2 Name  |  | CARD ST   |   |                       |        |            |                             |       |
| Stop Condition-Street 1  |  | None  |   |                       |        |            |                             |       |
| Total Cost:  |  | \$ 3200.00  |   |                       |        |            |                             |       |

|                         |            |
|-------------------------|------------|
| Street 1 Name           | RAPHEAL PL |
| Stop Condition-Street 2 | StopSign   |
| Street 2 Name           | CARD ST    |
| Stop Condition-Street 1 | None       |

Total Cost: \$ 3200.00

