

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 23895 Main Street: BATTLE\_FOREST\_DR Cross Street: REA\_RD Location: NE **Overall Compliance: No** ADA ID: 224B5DD977B8 Ramp Type: Directional1 Initial Pass/Fail: Fail **Severity Score:** 25

**Codes/Mitigation Info/Possible Solution** 



Street 1 Name	BATTLE FOREST DR
Stop Condition-Street 1	StopSign
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Possible Solutions:			
Remove & Replace Entire Ramp.			
	,		
	,		
	l		
	l		
Surveyor Notes:	l I		
N/A	1		
	I		
	I		
	ı		
PROW/ADA:	ı		
R304.5.3	ı		

Total Cost:	\$ 1600.00

Field Measurements/Component Compliance								
Compl	iance	Description	Data	Com	pliance	Description	Data	
N/A	Ram	p Length (in)	66.0	N/A	Grad	e Break?	N/A	
Yes	Ram	p Width (in)	48.0	N/A	Grad	e Break Slope (%)	0.0	
Yes	Ram	p Slope (%)	3.9	N/A	N/A Grade Break XSlope (%)		0.0	
No	Ram	p XSlope (%)	8.1					
N/A	Flare	Type LT	N/A	N/A	Flare Type RT		N/A	
N/A	Flare	e Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	0.0	
N/A	Flare	Traversable LT?	N/A	N/A	Flare Traversable RT?		N/A	
N/A	Land	ing Length (in)	0.0	N/A	DWS	Provided?	N/A	
N/A	Land	ing Width (in)	0.0	N/A	DWS	Contrast?	N/A	
N/A	Land	ing Slope (%)	0.0	N/A	DWS	Length (in)	N/A	
N/A	Land	ing X Slope (%)	0.0	N/A	DWS	Full Width?	N/A	
N/A	Land	ing Curb? (Y/N)	N/A	N/A	DWS	Offset LT (in)	N/A	
N/A	Share	ed Landing?	N/A	N/A	DWS	Offset RT (in)	N/A	
N/A	Gutte	er Ponding?	0.0	N/A	Gutte	er Slope (%)	N/A	
N/A	Gutte	er Lip Ht (in)	0.0	N/A	Gutte	er X Slope (%)	N/A	
N/A	Paint	ed X Walk1?	No		Road	Slope (%)	3.9	
	X Wa	alk 1 Direction	To SW		Road	I X Slope (%)	6.1	
	X Wa	alk 1 Width (in)	N/A		Clea	r Space?	N/A	
	X Wa	alk 1 Slope (%)	3.9	N/A	Clea	r Space to XWalk (in)	N/A	
	X Wa	alk 1 X Slope (%)	6.1	N/A	Storr	n Grate/Utility Hazard?	N/A	
N/A	Ram	p inside XWalk1?	N/A		Storr	n Grate/Utility Type		
N/A	Any (	Obstructions?	N/A				N/A	
	Obst	ruction Type		Yes	Surfa	ace Condition? (G/P)	Good	
			N/A	N/A	Curb	Slope (%)	4.2	





