

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 52288 Main Street: STEELE CREEK RD **Cross Street: DIXIE RIVER RD** Location: Ε

ADA ID: 22B3ABFFCD32 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 8.75

## **Codes/Mitigation Info/Possible Solution**



**DIXIE RIVER RD** Street 1 Name Stop Condition-Street 2 Signal Street 2 Name STEELE CREEK RD Stop Condition-Street 1 Signal Possible Solutions: Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent. Surveyor Notes: N/A PROW/ADA: R304.5.1

Total Cost: 3200.00

Field Measurements/Component Compliance							
	Compliance Description		Data	Compliance Description		Description	Data
	N/A	Ramp Length (in)	96.0	Yes	Ramp	Slope (%)	5.3
	No	Ramp Width (in)	47.0	Yes	Ramp	XSlope (%)	1.5
	N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
	N/A	Painted X Walk1?	Yes	N/A	Paint	ed X Walk2?	Yes
		X Walk 1 Direction	To SW		X Wa	lk 2 Direction	To NW
	N/A	X Walk 1 Width (in)	108.0	N/A	X Wa	lk 2 Width (in)	111.0
		X Walk 1 Slope (%)	2.5		X Wa	lk 2 Slope (%)	0.5
		X Walk 1 X Slope (%)	0.3		X Wa	lk 2 X Slope (%)	3.0
	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp	inside XWalk2?	Yes
		Road Slope (%)	2.7	N/A	Clear	Space?	N/A
		Road X Slope (%)	2.3	N/A	Clear	Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm	n Grate/Utility Hazard?	N/A
		Obstruction Type			Storm	n Grate/Utility Type	
			N/A				N/A
				Yes	Surfa	ce Condition? (G/P)	Good





