

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			-						
Intersection ID: 12818	Main Street: SCHOOL_ST			Cross Street: THE_PLAZA				Location:	NW
ADA ID: 22E0EE976249	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: N			nce: N	o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Entire Rai	np.	N/A	Ramp Length (in)	74.0	N/A	Grade Break?	N/A
			•	Yes	Ramp Width (in)	62.5	N/A	Grade Break Slope (%)	0.0
a the second of the	11 34			No	Ramp Slope (%)	9.5	N/A	Grade Break XSlope (%)	0.0
	TKEE			No	Ramp XSlope (%)	4.3			
	1 lisey			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		3		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
Sehool ST &		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	A Starting	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
	M			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	EL C			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
Last Market Market	A. Water	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
		R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
		·····, ·····		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	State 1			N/A	Gutter Lip Ht (in)	1.0	N/A	Gutter X Slope (%)	N/A
Part 19 - Allow Parts				N/A	Painted X Walk1?	No		Road Slope (%)	3.8
Street 1 Name	SCHOOL ST	_			X Walk 1 Direction	To S		Road X Slope (%)	5.1
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	3.8	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	5.1	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	1.0

