

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                                         |                                    |                                         |                        |
|-----------------------------------------|------------------------------------|-----------------------------------------|------------------------|
| Intersection ID: N/A                    | Main Street: BRADSTREET COMMONS WY | Cross Street: ROTHMAN LN                | Location: SE           |
| ADA ID: 22E547C8AB69                    | Ramp Type: Combination2Diag        | Initial Pass/Fail: Fail                 | Overall Compliance: No |
| Severity Score: 0                       |                                    |                                         |                        |
| Codes/Mitigation Info/Possible Solution |                                    | Field Measurements/Component Compliance |                        |



Possible Solutions:

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.**

Surveyor Notes:

**N/A**

PROW/ADA:

**Not Found, R304.5.1, R304.5.1, R304.2.2, R304.5.3**

Total Cost:

**\$ 3200.00**

| Compliance | Description              | Data  | Compliance | Description                 | Data  |
|------------|--------------------------|-------|------------|-----------------------------|-------|
| N/A        | Ramp Length LT (in)      | 42.0  | N/A        | Ramp Length RT (in)         | 48.0  |
| No         | Ramp Width LT (in)       | 47.0  | No         | Ramp Width RT (in)          | 47.0  |
| Yes        | Ramp Slope LT (%)        | 4.3   | Yes        | Ramp Slope RT (%)           | 5.3   |
| Yes        | Ramp XSlope LT (%)       | 1.8   | No         | Ramp XSlope RT (%)          | 2.6   |
| N/A        | Ramp Length (in)         | 48.5  | No         | Ramp Slope (%)              | 11.0  |
| No         | Ramp Width (in)          | 46.5  | No         | Ramp XSlope (%)             | 2.4   |
| N/A        | Flare Type LT            | N/A   | N/A        | Flare Type RT               | N/A   |
| N/A        | Flare Slope LT (%)       | N/A   | N/A        | Flare Slope RT (%)          | N/A   |
| N/A        | Flare Traversable LT?    | N/A   | N/A        | Flare Traversable RT?       | N/A   |
| N/A        | Landing Length (in)      | N/A   | N/A        | DWS Provided?               | N/A   |
| N/A        | Landing Width (in)       | N/A   | N/A        | DWS Contrast?               | N/A   |
| N/A        | Landing Slope (%)        | N/A   | N/A        | DWS Length (in)             | N/A   |
| N/A        | Landing X Slope (%)      | N/A   | N/A        | DWS Full Width?             | N/A   |
| N/A        | Landing Curb? (Y/N)      | N/A   | N/A        | DWS Offset (in)             | N/A   |
| N/A        | Shared Landing?          | N/A   |            |                             |       |
| N/A        | Gutter Ponding?          | N/A   | N/A        | Gutter Slope (%)            | N/A   |
| N/A        | Gutter Lip Ht (in)       | N/A   | N/A        | Gutter X Slope (%)          | N/A   |
| N/A        | Painted X Walk1?         | No    | N/A        | Painted X Walk2?            | No    |
|            | X Walk 1 Direction       | To NW |            | X Walk 2 Direction          | To SW |
|            | X Walk 1 Width (in)      | N/A   |            | X Walk 2 Width (in)         | N/A   |
|            | X Walk 1 Slope (%)       | 0.1   |            | X Walk 2 Slope (%)          | 0.4   |
|            | X Walk 1 X Slope (%)     | 3.2   |            | X Walk 2 X Slope (%)        | 2.5   |
| N/A        | Ramp inside XWalk1?      | N/A   | N/A        | Ramp inside XWalk2?         | N/A   |
|            | Road Slope (%)           | 1.8   |            | Clear Space?                | N/A   |
|            | Road X Slope (%)         | 2.4   | N/A        | Clear Space to XWalk (in)   | N/A   |
|            |                          |       | N/A        | Any Obstruction?            | N/A   |
|            |                          |       |            | Obstruction Type            | N/A   |
|            |                          |       | N/A        | Storm Grate/Utility Hazard? | N/A   |
|            |                          |       |            | Storm Grate/Utility Type    | N/A   |
| Yes        | Surface Condition? (G/P) | Good  |            |                             |       |
|            | Curb Slope (%)           | 10.2  |            |                             |       |

