

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 47662Main Street: CANDLESTICK_CTCross Street: COMISKEY_LNLocation:NWADA ID: 22E69EFED643Ramp Type: BlendTrans1Initial Pass/Fail: FailOverall Compliance: NoSeverity Score:10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name COMISKEY LN
Stop Condition-Street 1 None
Street 2 Name CANDLESTICK CT
Stop Condition-Street 2 StopSign

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.1, R304.5.3

PROW/ADA:
R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Compliance Description Data Compliance Description Data	
N/A Ramp Length (in) 46.0 Yes BlendTrans Slope (%)	
No Ramp Width (in) 46.0 No BlendTrans XSlope (%)	
N/A Flare Type LT N/A N/A Flare Type RT	N/A
N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%)	N/A
N/A Flare Traversable LT? N/A N/A Flare Traversable RT?	
N/A Landing Length (in) N/A N/A DWS Provided?	N/A
N/A Landing Width (in) N/A N/A DWS Contrast?	N/A
N/A Landing Slope (%) N/A N/A DWS Length (in)	N/A
N/A Landing X Slope (%) N/A N/A DWS Full Width?	N/A
N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in)	N/A
N/A Shared Landing? N/A	N/A
N/A Gutter Ponding? N/A N/A Gutter Slope (%)	N/A
N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%)	N/A
N/A Painted X Walk1? No N/A Painted X Walk2?	N/A No
X Walk 1 Direction To S X Walk 2 Direction	To E
X Walk 1 Width (in) N/A X Walk 2 Width (in)	N/A
X Walk 1 Slope (%) 3.8 X Walk 2 Slope (%)	3.3
X Walk 1 X Slope (%) 3.4 X Walk 2 X Slope (%)	
N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2?	
Road Slope (%) 0.4 Clear Space?	N/A
Road X Slope (%) 4.3 N/A Clear Space to XWalk	` '
N/A Any Obstructions? N/A N/A Storm Grate/Utility Ha	zard? N/A
Obstruction Type Storm Grate/Utility Type	oe
N/A	N/A
Yes Surface Condition? (G	G/P) Good
N/A Curb Slope (%)	2.3





