


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10040110	Main Street: TUCKASEEGEE_RD	Cross Street: N/A	Location: S
ADA ID: 22FF5C4CFBCA	Ramp Type: BlendTrans2	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 8.75	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		Yes	BlendTrans Slope (%)	1.5
			No	BlendTrans XSlope (%)	0.1
			N/A	Flare Type LT	N/A
			N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	N/A
			N/A	Painted X Walk2?	N/A
			N/A	X Walk 1 Direction	N/A
			N/A	X Walk 2 Direction	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.5.1</p>			Data	Description	Data
			52.5	Ramp Length (in)	N/A
			47.5	Ramp Width (in)	N/A
			N/A	Flare Type LT	N/A
			N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter X Slope (%)	N/A
			No	Painted X Walk1?	N/A
			To N	Painted X Walk2?	N/A
			N/A	X Walk 1 Direction	N/A
			N/A	X Walk 2 Direction	N/A
<p>Street 1 Name</p> <p>Stop Condition-Street 1</p> <p>Street 2 Name</p> <p>Stop Condition-Street 2</p>			0.6	X Walk 1 Width (in)	N/A
			0.6	X Walk 1 Slope (%)	N/A
			1.0	X Walk 2 Width (in)	N/A
			1.0	X Walk 2 Slope (%)	N/A
			1.0	X Walk 2 X Slope (%)	N/A
			N/A	X Walk 1 X Slope (%)	N/A
			N/A	Ramp inside XWalk1?	N/A
			N/A	Ramp inside XWalk2?	N/A
			1.0	Road Slope (%)	N/A
			0.6	Clear Space?	N/A
			0.6	Clear Space to XWalk (in)	N/A
			N/A	Road X Slope (%)	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Storm Grate/Utility Type	N/A
			N/A	Any Obstructions?	N/A
			N/A	Obstruction Type	N/A
			N/A	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	0.1

Total Cost: \$ 3200.00

