

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

Intersection ID: 12303 Main Street: BELVEDERE_AV Cross Street: ST_ANDREWS_LN Location: SE

ADA ID: 232C29D34CA9 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Data



Street 1 Name
Stop Condition-Street 2
StopSign
Street 2 Name
N/A
Stop Condition-Street 1
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

N/A Ramp Length (in)
No Ramp Width (in)
N/A Flare Type LT
N/A Flare Slope LT (%)
N/A Landing Length (in)
N/A Landing Length (in)
N/A Landing Width (in)
N/A Landing Slope (%)
N/A Landing Slope (%)
N/A Landing X Slope (%)
N/A Landing Curb? (Y/N
N/A Shared Landing?
PROW/ADA:
Not Found, R304.5.1, R304.2.2

N/A Gutter Ponding?
N/A Gutter Lip Ht (in)
N/A Painted X Walk 1?
X Walk 1 Direction
N/A X Walk 1 Width (in)
X Walk 1 Slope (%)
X Walk 1 X Slope (%)
N/A Ramp inside XWalk
Road Slope (%)







Total Cost:



1850.00