


# Access Compliance Report

## Public Rights-of-Way (Curb Ramps)

Intersection ID: 17446		Main Street: HILLSIDE_AV		Cross Street: WILLOW_OAK_RD		Location: SW			
ADA ID: 235EBD379EB2		Ramp Type: Combination1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 50	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
 <div>Possible Solutions:</div> <div>Remove &amp; Replace Entire Ramp.</div> <div>Surveyor Notes:</div> <div>N/A</div> <div>PROW/ADA:</div> <div>Not Found, R304.5.3, R304.3.2</div> <div>Street 1 Name</div> <div>None</div> <div>Stop Condition-Street 1</div> <div>HILLSIDE_AV</div> <div>Street 2 Name</div> <div>N/A</div> <div>Stop Condition-Street 2</div> <div>N/A</div>				Compliance	Description	Data	Compliance	Description	Data
				N/A	Ramp Length LT (in)	36.0	N/A	Ramp Length RT (in)	34.0
				Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	60.0
				Yes	Ramp Slope LT (%)	5.0	No	Ramp Slope RT (%)	18.4
				No	Ramp XSlope LT (%)	2.1	No	Ramp XSlope RT (%)	4.9
				N/A	Ramp Length (in)	29.5	Yes	Ramp Slope (%)	2.5
				Yes	Ramp Width (in)	50.0	No	Ramp XSlope (%)	7.9
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A				
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A				
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A				
N/A	Shared Landing?	N/A							
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A				
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A				
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A				
	X Walk 1 Direction	To N		X Walk 2 Direction	N/A				
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A				
	X Walk 1 Slope (%)	3.9		X Walk 2 Slope (%)	N/A				
	X Walk 1 X Slope (%)	8.2		X Walk 2 X Slope (%)	N/A				
	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A				
	Road Slope (%)	N/A		Clear Space?	N/A				
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A				
			N/A	Any Obstruction?	N/A				
				Obstruction Type	N/A				
			N/A	Storm Grate/Utility Hazard?	N/A				
				Storm Grate/Utility Type	N/A				
			Yes	Surface Condition? (G/P)	Good				
				Curb Slope (%)	8.7				

