

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 6264 Mai | Main Street: FAIRES FARM RD | | Cross Street: GORDON_WALTERS_DR | | | Location: | Ν |
|---|---|---|---------------------------------|------|-----------------------------|-----------------------------|------|
| | | | | | | | 8.75 |
| · · · · | | | | | | 0.75 | |
| Codes/Mitigation Info/Possible Solution | | Field Measurements/Component Compliance | | | | | |
| CORDON WANTERS DR | Possible Solutions: | Com | Compliance Description | | Data Compliance Description | | Data |
| | Remove & Replace Entire Ramp | . N/A | Ramp Length (in) | 48.0 | Yes | Ramp Slope (%) | 7.5 |
| | | No | Ramp Width (in) | 47.0 | Yes | Ramp XSlope (%) | 0.4 |
| | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | 1 | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | Surveyor Notes: | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | N/A | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | and the second se | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | Field and a second s | N/A | Shared Landing? | N/A | | | |
| | PROW/ADA: | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | Not Found, R304.5.1 | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | | | X Walk 1 Direction | To E | | X Walk 2 Direction | N/A |
| | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name FAIRES FARM | RD | | X Walk 1 Slope (%) | 5.1 | | X Walk 2 Slope (%) | N/A |
| Stop Condition-Street 2 N | one | | X Walk 1 X Slope (%) | 5.1 | | X Walk 2 X Slope (%) | N/A |
| Street 2 Name | N/A | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | N/A | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Total Cost: \$ | 850.00 | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | N/A | | | N/A |

Yes Surface Condition? (G/P)

Good

