

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 18234	Main Street: PARK_RD	Cross Street: E_WOODLAWN_RD	Location: NE
ADA ID: 239534BCC6C7	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
Severity Score: 0			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.2

Total Cost:

\$ 1600.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	91.0	No	Grade Break?	No
Yes	Ramp Width (in)	55.0	N/A	Grade Break Slope (%)	7.0
Yes	Ramp Slope (%)	7.1	N/A	Grade Break XSlope (%)	2.0
Yes	Ramp XSlope (%)	0.5			
Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	69.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	55.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	1.2	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	1.4	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset LT (in)	1.0
N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	13.0
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.6
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	3.9
N/A	Painted X Walk1?	Yes		Road Slope (%)	3.0
	X Walk 1 Direction	To SE		Road X Slope (%)	5.7
	X Walk 1 Width (in)	91.0		Clear Space?	Yes
	X Walk 1 Slope (%)	3.0	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	5.7	Yes	Storm Grate/Utility Hazard?	No
Yes	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	4.1

Street 1 Name E WOODLAWN RD

Stop Condition-Street 1 Signal

Street 2 Name N/A

Stop Condition-Street 2 N/A

