


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 25747	Main Street: HAMILTON_RD	Cross Street: SMITH_RD	Location: NE
ADA ID: 23D626E62AF6	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 25	

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance						
	Possible Solutions:	<b>Remove &amp; Replace Entire Ramp.</b>						
	Surveyor Notes:	<b>N/A</b>						
	PROW/ADA:	<b>R304.5.3</b>						
	Street 1 Name	<b>SMITH RD</b>						
	Stop Condition-Street 1	<b>None</b>						
	Street 2 Name	<b>N/A</b>						
	Stop Condition-Street 2	<b>N/A</b>						
	Total Cost:	\$	<b>1600.00</b>					
			<b>Compliance</b>	<b>Description</b>	<b>Data</b>	<b>Compliance</b>	<b>Description</b>	<b>Data</b>
			<b>N/A</b>	Ramp Length (in)	<b>133.0</b>	<b>N/A</b>	Grade Break?	<b>N/A</b>
		<b>Yes</b>	Ramp Width (in)	<b>60.0</b>	<b>N/A</b>	Grade Break Slope (%)	<b>0.0</b>	
		<b>Yes</b>	Ramp Slope (%)	<b>6.1</b>	<b>N/A</b>	Grade Break XSlope (%)	<b>0.0</b>	
		<b>No</b>	Ramp XSlope (%)	<b>8.5</b>				
		<b>N/A</b>	Flare Type LT	<b>N/A</b>	<b>N/A</b>	Flare Type RT	<b>N/A</b>	
		<b>N/A</b>	Flare Slope LT (%)	<b>N/A</b>	<b>N/A</b>	Flare Slope RT (%)	<b>0.0</b>	
		<b>N/A</b>	Flare Traversable LT?	<b>N/A</b>	<b>N/A</b>	Flare Traversable RT?	<b>N/A</b>	
		<b>N/A</b>	Landing Length (in)	<b>0.0</b>	<b>N/A</b>	DWS Provided?	<b>N/A</b>	
		<b>N/A</b>	Landing Width (in)	<b>0.0</b>	<b>N/A</b>	DWS Contrast?	<b>N/A</b>	
		<b>N/A</b>	Landing Slope (%)	<b>0.0</b>	<b>N/A</b>	DWS Length (in)	<b>N/A</b>	
		<b>N/A</b>	Landing X Slope (%)	<b>0.0</b>	<b>N/A</b>	DWS Full Width?	<b>N/A</b>	
		<b>N/A</b>	Landing Curb? (Y/N)	<b>N/A</b>	<b>N/A</b>	DWS Offset LT (in)	<b>N/A</b>	
		<b>N/A</b>	Shared Landing?	<b>N/A</b>	<b>N/A</b>	DWS Offset RT (in)	<b>N/A</b>	
		<b>N/A</b>	Gutter Ponding?	<b>0.0</b>	<b>N/A</b>	Gutter Slope (%)	<b>N/A</b>	
		<b>N/A</b>	Gutter Lip Ht (in)	<b>0.0</b>	<b>N/A</b>	Gutter X Slope (%)	<b>N/A</b>	
		<b>N/A</b>	Painted X Walk1?	<b>No</b>				
			X Walk 1 Direction	<b>To NW</b>				
			X Walk 1 Width (in)	<b>N/A</b>				
			X Walk 1 Slope (%)	<b>0.0</b>	<b>N/A</b>	Clear Space?	<b>N/A</b>	
			X Walk 1 X Slope (%)	<b>4.3</b>	<b>N/A</b>	Clear Space to XWalk (in)	<b>N/A</b>	
		<b>N/A</b>	Ramp inside XWalk1?	<b>N/A</b>				
		<b>N/A</b>	Any Obstructions?	<b>N/A</b>				
			Obstruction Type		<b>Yes</b>	Storm Grate/Utility Hazard?	<b>N/A</b>	
						Storm Grate/Utility Type		
					<b>Yes</b>	Surface Condition? (G/P)	<b>Good</b>	
					<b>N/A</b>	Curb Slope (%)	<b>4.8</b>	

