


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 18301	Main Street: MCLAUGHLIN_DR	Cross Street: OLD_POST_RD	Location: NE
ADA ID: 246C8E545149	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 21.25

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance						
	Possible Solutions:	Compliance	Description	Data	Compliance	Description	Data	
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	N/A	Ramp Length (in)	49.0	No	Ramp Slope (%)	8.8	
		No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	1.0	
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A			
Surveyor Notes:	N/A	N/A	Shared Landing?	N/A				
		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	PROW/ADA:	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
			X Walk 1 Direction	To W		X Walk 2 Direction	To S	
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
			X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	4.0	
			X Walk 1 X Slope (%)	4.0		X Walk 2 X Slope (%)	3.8	
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
			Road Slope (%)	4.8	N/A	Clear Space?	N/A	
	Road X Slope (%)	0.4	N/A	Clear Space to XWalk (in)	N/A			
Total Cost:	\$	3200.00	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
				Obstruction Type			Storm Grate/Utility Type	
					N/A		N/A	
					Yes	Surface Condition? (G/P)	Good	

