cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 45548	Main Street: KORP_RD		Street:	PEACHTREE_RD	Location:	N		
ADA ID: 249DE8F2565F	F2565F Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance:			nce: N	o Severity Score:	25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:					a Compliance Description		Data
	Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	48.5	Yes	Ramp Slope (%)	7.4
	Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	9.2
	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	ALL		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	A. A.		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A A A A A A A A A A A A A A A A A A A			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
34	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
BALL STATE	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
E Contraction			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A
A A STATE AND A STATE A			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name PEACHT	REE RD			X Walk 1 Slope (%)	5.5		X Walk 2 Slope (%)	9.7
Stop Condition-Street 2	None			X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	5.0
Street 2 Name K	ORP RD		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 S	StopSign			Road Slope (%)	7.7	N/A	Clear Space?	N/A
				Road X Slope (%)	2.7	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

