

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15984	Main Street: LANIER_AV			eet.	UNAKA_AV	Location:	Е		
ADA ID: 24DF03C204D3 Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No					o Severity Score:	1.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	and the	Possible Solutions:	Compliance Description			Data Compliance Description			Data
S Fret -	and the	Remove & Replace Entire Ramp	, N	/ A	Ramp Length (in)	45.0	N/A	Grade Break?	N/A
	THE W		Ye	es	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0
			Ye	es	Ramp Slope (%)	7.4	N/A	Grade Break XSlope (%)	0.0
	1 10		N	0	Ramp XSlope (%)	2.6			
Non Land	All and a second		N	/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
TER		d	N	/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
E Protection	1 C	Surveyor Notes:	N	/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
the second second	De Kon	N/A	N	/ A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
	~		N	/ A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
G	110		N	/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	5 6 . 4		N	/ A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:	N	/ A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	- And	R304.5.3	N	/ A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	S		N	/ A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
			N	/ A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
			N	/ A	Painted X Walk1?	No		Road Slope (%)	3.2
Street 1 Name	UNAKA AV				X Walk 1 Direction	To SW		Road X Slope (%)	3.5
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	3.2	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	3.5	N/A	Storm Grate/Utility Hazard?	N/A
			N	/ A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
			N	/ A	Any Obstructions?	N/A			N/A
		Total Cost: \$	600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	14.7

