

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

44.0

58.0

14.1

0.4

6.1

3.2

N/A

N/A

N/A

N/A

N/A

Good

6.4

Intersection ID: 17945 Main Street: E WOODLAWN RD **Cross Street: MURRAYHILL RD** Location: SW **Overall Compliance: No** Severity Score: 26.25 ADA ID: 254B98603177 Ramp Type: Combination2 Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution

Total Cost:

Field Measurements/Component Compliance

N/A

Yes

No

Yes

Yes

No

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

Flare Traversable RT?

Surface Condition? (G/P)

Curb Slope (%)

Data

N/A

N/A

N/A

N/A

25.0

48.0

N/A

N/A

N/A

N/A

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



StopSign Street 1 Name Stop Condition-Street 1 MURRAYHILL RD N/A Street 2 Name Stop Condition-Street 2 N/A

Compliance Description Possible Solutions: N/A Remove & Replace Entire Ramp. N/A N/A N/A N/A Yes Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.3, R304.3.2



1600.00

Landing Slope (%) N/A N/A DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? N/A N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A N/A Gutter Lip Ht (in) 1.0 Gutter X Slope (%) N/A N/A Painted X Walk2? N/A Painted X Walk1? No N/A To SE X Walk 1 Direction X Walk 2 Direction N/A X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A X Walk 2 Slope (%) 5.2 N/A X Walk 1 Slope (%) X Walk 1 X Slope (%) 4.1 X Walk 2 X Slope (%) N/A N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A

Yes

