


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10113	Main Street: LAKE_AV	Cross Street: RUSH_AV	Location: W
ADA ID: 259B950D2EFB	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance									
	Possible Solutions:		Compliance			Description			Data			
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)		64.0		N/A	Grade Break?		N/A	
			Yes	Ramp Width (in)		48.0		N/A	Grade Break Slope (%)		0.0	
			No	Ramp Slope (%)		10.0		N/A	Grade Break XSlope (%)		0.0	
			No	Ramp XSlope (%)		2.3						
			N/A	Flare Type LT		N/A		N/A	Flare Type RT		N/A	
			N/A	Flare Slope LT (%)		N/A		N/A	Flare Slope RT (%)		0.0	
			N/A	Flare Traversable LT?		N/A		N/A	Flare Traversable RT?		N/A	
			N/A	Landing Length (in)		0.0		N/A	DWS Provided?		N/A	
			N/A	Landing Width (in)		0.0		N/A	DWS Contrast?		N/A	
		N/A	Landing Slope (%)		0.0		N/A	DWS Length (in)		N/A		
		N/A	Landing X Slope (%)		0.0		N/A	DWS Full Width?		N/A		
		N/A	Landing Curb? (Y/N)		N/A		N/A	DWS Offset LT (in)		N/A		
		N/A	Shared Landing?		N/A		N/A	DWS Offset RT (in)		N/A		
		N/A	Gutter Ponding?		0.0		N/A	Gutter Slope (%)		N/A		
		N/A	Gutter Lip Ht (in)		0.0		N/A	Gutter X Slope (%)		N/A		
		N/A	Painted X Walk1?		No			Road Slope (%)		1.9		
			X Walk 1 Direction		To E			Road X Slope (%)		5.7		
			X Walk 1 Width (in)		N/A			Clear Space?		N/A		
			X Walk 1 Slope (%)		1.9		N/A	Clear Space to XWalk (in)		N/A		
			X Walk 1 X Slope (%)		5.7		N/A	Storm Grate/Utility Hazard?		N/A		
		N/A	Ramp inside XWalk1?		N/A			Storm Grate/Utility Type				
		N/A	Any Obstructions?		N/A					N/A		
			Obstruction Type				Yes	Surface Condition? (G/P)		Good		
							N/A	Curb Slope (%)		N/A		

