

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10022367 Main Street: CAMFIELD ST **Cross Street: N/A** Location: NE ADA ID: 25AEE54144B9 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 10

Codes/Mitigation Info/Possible Solution



ENTRANCE Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name **CAMFIELD ST** Stop Condition-Street 1 None Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.5.3

Total Cost: 3200.00

Field Measurements/Component Compliance						
	Compliance Description		Data	Compl	iance Description	Data
	N/A	Ramp Length (in)	94.5	Yes	Ramp Slope (%)	5.2
	No	Ramp Width (in)	40.5	No	Ramp XSlope (%)	3.1
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	N/A	Shared Landing?	N/A			
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To W		X Walk 2 Direction	To S
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	2.0
		X Walk 1 X Slope (%)	2.5		X Walk 2 X Slope (%)	0.2
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	1.9	N/A	Clear Space?	N/A
		Road X Slope (%)	1.6	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type			Storm Grate/Utility Type	
			N/A			N/A
				Yes	Surface Condition? (G/P)	Good
Ŋ.	1.48					





