

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.5

3.3

N/A

Good

Cross Street: N/A Intersection ID: 10014673 Main Street: MCCLINTOCK RD Location: NE Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 25C67B677078 Ramp Type: Perp Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

76.0

48.0

N/A

No

N/A

2.3

4.8

N/A

N/A

N/A

N/A

N/A

To SW

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?



	The state of the s
Street 1 Name	MCCLINTOCK RD
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:	Compli	ance Description
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)
·	Yes	Ramp Width (in)
	N/A	Flare Type LT
	N/A	Flare Slope LT (%)
	N/A	Flare Traversable L
	N/A	Landing Length (in)
Surveyor Notes:	N/A	Landing Width (in)
N/A	N/A	Landing Slope (%)
	N/A	Landing X Slope (%
	N/A	Landing Curb? (Y/N
	N/A	Shared Landing?
PROW/ADA:	N/A	Gutter Ponding?
Not Found, R304.2.2	N/A	Gutter Lip Ht (in)
	N/A	Painted X Walk1?
		X Walk 1 Direction
	N/A	X Walk 1 Width (in)
		X Walk 1 Slope (%)
		X Walk 1 X Slope (%
	N/A	Ramp inside XWalk

(Sersion tra)



Total Cost:



N/A

1850.00