

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8225 Main Street: SOFLEY\_RD Cross Street: W\_SUGAR\_CREEK\_RD Location: NW

ADA ID: 262C656DBAFA Ramp Type: Para Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 43.75

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

SOFLEY RD StopSign W SUGAR CREEK RD None

Possible Solutions:	
Remove & Replace Entire Ramp.	ı
	ı
	•
	•
	ı
	ı
Surveyor Notes:	ı
NO LT SW, LT RP < 5%	ı
	ı
	ı
	ı
PROW/ADA:	1
R304.5.1, R304.3.2, R304.5.3	ı
	1
	_
	ı

Total Cost: \$ 1600.00

Data	liance Description	Compliance Description		oliance Description Data	
53.0	Ramp Length RT (in)	N/A	64.0	Ramp Length LT (in)	N/A
35.0	Ramp Width RT (in)	No	35.0	Ramp Width LT (in)	No
13.4	Ramp Slope RT (%)	No	4.6	Ramp Slope LT (%)	Yes
3.1	Ramp XSlope RT (%)	No	0.4	Ramp XSlope LT (%)	Yes
N/A	DWS Provided?	N/A	N/A	Landing Length (in)	N/A
N/A	DWS Contrast?	N/A	N/A	Landing Width (in)	N/A
N/A	DWS Length (in)	N/A	N/A	Landing Slope (%)	N/A
N/A	DWS Full Width?	N/A	N/A	Landing X Slope (%)	N/A
N/A	DWS Offset (in)	N/A	N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
N/A	Gutter Slope (%)	N/A	N/A	Gutter Ponding?	N/A
N/A	Gutter X Slope (%)	N/A	N/A	Gutter Lip Ht (in)	N/A
No	Painted X Walk2?	N/A	No	Painted X Walk1?	N/A
To E	X Walk 2 Direction		To S	X Walk 1 Direction	
N/A	X Walk 2 Width (in)	N/A	N/A	X Walk 1 Width (in)	N/A
4.6	X Walk 2 Slope (%)		1.1	X Walk 1 Slope (%)	
1.0	X Walk 2 X Slope (%)		6.0	X Walk 1 X Slope (%)	
N/A	Ramp inside XWalk2?	N/A	N/A	Ramp inside XWalk1?	N/A
N/A	Clear Space?	N/A	6.1	Road Slope (%)	
N/A	Clear Space to XWalk (in)	N/A	1.5	Road X Slope (%)	
N/A	Storm Grate/Utility Hazard?	N/A	N/A	Any Obstructions?	N/A
	Storm Grate/Utility Type			Obstruction Type	
N/A			N/A		
Good	Surface Condition? (G/P)	Yes			
31.0	Curb Slope (%)	N/A			





