

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Cross	Cross Street: KILBORNE_DR				Location:	NE				
ADA ID: 26BC4228E144	Ramp Type: Combination1				Initial Pass/Fail: Fail Overall Complianc				ce: No Severity Score: 10		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	The second second	Possible Solutions:		Compliance Description			Data Compliance Description			Data	
	84	Remove & Replac	e Entire Ramp		N/A	Ramp Length LT (in)	58.5	N/A	Ramp Length RT (in)	56.5	
	1				Yes	Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	58.5	
	and the second second				Yes	Ramp Slope LT (%)	6.8	Yes	Ramp Slope RT (%)	2.6	
					No	Ramp XSlope LT (%)	2.4	No	Ramp XSlope RT (%)	2.8	
	aus aus				N/A	Ramp Length (in)	24.0	Yes	Ramp Slope (%)	6.5	
	a' 1/10 -				No	Ramp Width (in)	46.5	Yes	Ramp XSlope (%)	1.8	
		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	· ·				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
Martin Barrier	1				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	All and a start of the	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	A PART A TH	Not Found, R304	5.1, R304.5.3		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	1 3 A 12				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	Se I e				N/A	Shared Landing?	N/A				
	19.80				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	ELKIN LN				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To S		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$ 1	800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
A A A A A A A A A A A A A A A A A A A		Call 9		Office of the				N/A	Any Obstruction?	N/A	
									Obstruction Type		
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			10	and the second second					N/A	
141 3 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					1			N/A	Storm Grate/Utility Hazard?	N/A	
					101				Storm Grate/Utility Type	N/A	
				11	7					N/A	

N/A Surface Condition? (G/P) Yes Good Curb Slope (%) 19.3





