

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10031496 Main Street: MCKEE_RD Cross Street: N/A Location: SW

ADA ID: 27230BFE9180 Ramp Type: BlendTrans2 Initial Pass/Fail: Pass Overall Compliance: Yes Severity Score: 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name ENTRANCE
Stop Condition-Street 1 StopSign
Street 2 Name N/A
Stop Condition-Street 2 N/A

Possible Solutions:

N/A

N/A

Ramp Length (in)

Yes Ramp Width (in)

N/A

Flare Type LT

N/A

Flare Traversable L

N/A

Landing Length (in)

N/A

Surveyor Notes:

N/A

N/A

Landing Width (in)

N/A

N/A

Landing Slope (%)

N/A

Landing X Slope (%)

N/A

Landing Curb? (Y/N

N/A

Shared Landing?

PROW/ADA:

Yes

Gutter Ponding?

N/A

Yes

Gutter Lip Ht (in)

N/A

Painted X Walk 1

X Walk 1 Direction

X Walk 1 X Slope (%)

Total Cost: \$

Compliance Description		Data	Comp	liance Description	Data
N/A	Ramp Length (in)	71.0	Yes	BlendTrans Slope (%)	0.5
Yes	Ramp Width (in)	71.0	Yes	BlendTrans XSlope (%)	0.9
N/A	Flare Type LT	None	N/A	Flare Type RT	None
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
N/A	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
N/A	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.0
N/A	Landing X Slope (%)	N/A	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.0
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.7
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.0
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	0.1		Clear Space?	Yes
	Road X Slope (%)	1.3	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good

Yes

Curb Slope (%)

1.7







0.00