

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9015 Main Street: DEWOLFE_ST **Cross Street: TILLMAN RD** Location: **Overall Compliance: No** ADA ID: 274737100EBC Ramp Type: BlendTrans2 Initial Pass/Fail: Fail **Severity Score:** 10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



TILLMAN RD Street 1 Name Stop Condition-Street 1 StopSign Street 2 Name N/A Stop Condition-Street 2 N/A Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent.


Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3





Comp	liance Description	Data	Comp	liance Description	Data
N/A	Ramp Length (in)	106.0	Yes	BlendTrans Slope (%)	2.8
No	Ramp Width (in)	46.0	No	BlendTrans XSlope (%)	3.3
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	1.7		Clear Space?	N/A
	Road X Slope (%)	3.8	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
3-11: 0 13:11 0 13:11 1			No	Curb Slope (%)	11.5





Total Cost:

