

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

9.0

6.8

N/A

Good

Intersection ID: 10032512Main Street:N_CASWELL_RDCross Street:N/ALocation:NWADA ID: 2749EF176535Ramp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

No

N/A

Yes

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Flare Type RT

Data

74.0

48.0

N/A

No

To W

N/A

2.0

4.1

N/A

N/A

N/A

N/A

N/A



Street 1 Name	ENTRANCE
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:	Compli	ance	Description
Remove & Replace Entire Ramp.	N/A	Ramp	Length (in)
·	Yes	Ramp	Width (in)
	N/A	Flare	Type LT
	N/A	Flare	Slope LT (%)
	N/A	Flare	Traversable LT?
	N/A	Landi	ng Length (in)
Surveyor Notes:	N/A	Landi	ng Width (in)
N/A	N/A	Landi	ng Slope (%)
	N/A	Landi	ng X Slope (%)
	N/A	Landi	ng Curb? (Y/N)
	N/A	Share	ed Landing?
PROW/ADA:	N/A	Gutte	er Ponding?
Not Found, R304.2.2, R304.5.3	N/A	Gutte	er Lip Ht (in)
	N/A	Paint	ed X Walk1?
		X Wa	lk 1 Direction
	N/A	X Wa	lk 1 Width (in)
		X Wa	lk 1 Slope (%)
		X Wa	lk 1 X Slope (%)
	N/A	Ramp	inside XWalk1?
		Road	Slope (%)
		Road	X Slope (%)



Total Cost:



N/A

1850.00

Any Obstructions?

Obstruction Type