cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17854 Main Str	Main Street: HARDWICK_RD		reet:	N_SHARON_AMITY_	Location:	SW		
ADA ID: 276AE1980C33 Ramp T	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance: N			Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description			Data Compliance Description		
N.STURDON ANUT AR	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	lith	N/A	Ramp Length (in)	91.0	Yes	Ramp Slope (%)	6.5
			No	Ramp Width (in)	40.0	Yes	Ramp XSlope (%)	0.6
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	-		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	s		N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	5			X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name HARDWICK RD				X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	0.7
Stop Condition-Street 2 StopSign				X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	0.3
Street 2 Name N SHARON AMITY RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 None				Road Slope (%)	1.1	N/A	Clear Space?	N/A
				Road X Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

Yes Surface Condition? (G/P)

Good

