


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 7375	Main Street: TRYON_ST	Cross Street: TOM_HUNTER_RD	Location: SE
ADA ID: 278F0C4228BF	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 0	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Landing. Gutter Ponding Observed.		Yes	Ramp Length (in)	97.0
			Yes	Ramp Width (in)	96.0
			Yes	Flare Type L	Curbed_NoWalkSurface
			Yes	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	No
			Yes	Landing Length (in)	71.0
			Yes	Landing Width (in)	96.0
			No	Landing Slope (%)	2.2
			Yes	Landing X Slope (%)	0.5
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.2.2-Perp, R304.3.2-Para, R302.7</p>			Yes	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	No
			Yes	DWS Provided?	Yes
			Yes	DWS Contrast?	Yes
			Yes	DWS Length (in)	24.0
			Yes	DWS Full Width?	Yes
			Yes	DWS Offset (in)	0.0
			No	Gutter Ponding?	Yes
			Yes	Gutter Lip Ht (in)	0.0
			N/A	Painted X Walk1?	Yes
				X Walk 1 Direction	To W
			N/A	X Walk 1 Width (in)	108.0
				X Walk 1 Slope (%)	3.1
				X Walk 1 X Slope (%)	0.5
			Yes	Ramp inside XWalk1?	Yes
				Road Slope (%)	N/A
				Road X Slope (%)	N/A
			Yes	Any Obstructions?	No
				Obstruction Type	
Total Cost: \$ 1000.00			N/A		N/A
			Yes	Surface Condition? (G/P)	Good

