

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15094Main Street: ALBEMARLE_RDCross Street: REDDMAN_RDLocation: NWADA ID: 281EDCE5C5FARamp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name REDDMAN RD
Stop Condition-Street 2 Signal
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:				
Remove & Replace Entire Ramp.				
	N			
	N			
	1			
	1			
	1			
Surveyor Notes:	1			
N/A	1			
	1			
	1			
	1			
PROW/ADA:	1			
Not Found, R304.5.1, R304.2.2	N			
	1			
	1			
	N			
	r			



Total Cost:



1850.00

Comp	liance Description	Data	Comp	liance De	scription	Data
N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)		9.6
No	Ramp Width (in)	42.0	Yes	Ramp XSlope (%)		1.7
N/A	Flare Type LT	N/A	N/A	Flare Type RT		N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)		N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?		N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?		N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?		N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)		N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?		N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offs	set (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)		N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)		N/A
N/A	Painted X Walk1?	Yes	N/A	Painted X	(Walk2?	N/A
	X Walk 1 Direction	To E		X Walk 2	Direction	N/A
N/A	X Walk 1 Width (in)	110.0	N/A	X Walk 2	Width (in)	N/A
	X Walk 1 Slope (%)	1.2		X Walk 2	Slope (%)	N/A
	X Walk 1 X Slope (%)	0.4		X Walk 2	X Slope (%)	N/A
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp ins	ide XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Spa	ace?	N/A
	Road X Slope (%)	N/A	N/A	Clear Spa	ace to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Gr	ate/Utility Hazard?	N/A
	Obstruction Type			Storm Gr	ate/Utility Type	
		N/A				N/A
			Yes	Surface (Condition? (G/P)	Good