

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8943	Main Street: FREEDOM_DR			Street:	WESTSTONE_DR	Location:	SE		
ADA ID: 283116A77009	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Letter .	Possible Solutions:		Compliance Description Data Co			Comp	Compliance Description Data	
		Remove & Replace Entire Ramp		N/A	Ramp Length (in)	85.0	Yes	Ramp Slope (%)	7.8
	JAN -			No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	1.8
	and and			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
BI		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	A THE	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
COLEENIA				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
203	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			N/A	Shared Landing?	N/A			
All had		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A A A A A A A A A A A A A A A A A A A	Alexand			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
A CONTRACT OF ANY				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	<b>WESTONE DR</b>	_			X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

