

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 20146 Main Street: FAIRVIEW\_RD Cross Street: PARK\_SOUTH\_DR Location: NE

ADA ID: 283C512AE8A2 Ramp Type: Para Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 26.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
PARK SOUTH DR
Stop Condition-Street 1
Signal
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

N/A

Ye

Ye

Ye

N/A

Surveyor Notes:

LT RP < 5%

N/A

PROW/ADA:

R304.3.2, R304.5.3

Total Cost: \$ 1600.00

Constitute Production Party Component Compilation Production					
Compliance Description		Data	Compliance Description		Data
N/A	Ramp Length LT (in)	56.0	N/A	Ramp Length RT (in)	53.0
Yes	Ramp Width LT (in)	72.0	Yes	Ramp Width RT (in)	72.0
Yes	Ramp Slope LT (%)	2.6	No	Ramp Slope RT (%)	14.6
Yes	Ramp XSlope LT (%)	1.6	No	Ramp XSlope RT (%)	2.9
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	81.0	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	5.1		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
	••	N/A		, ,,	N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	7.8





