


Access Compliance Report

Public Rights-of-Way (Curb Ramps)

Intersection ID: 11803	Main Street: MECKLENBURG_AV	Cross Street: DANIEL_ST	Location: NW
ADA ID: 2847D6A1D591	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 1.25	

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance			
		Possible Solutions:			
		Remove & Replace Entire Ramp.			
<p>Surveyor Notes:</p> <p>N/A</p>					
<p>PROW/ADA:</p> <p>R304.5.3</p>					
Street 1 Name	DANIEL ST				
Stop Condition-Street 1	StopSign				
Street 2 Name	N/A				
Stop Condition-Street 2	N/A				
<p>Total Cost:</p> <p>\$ 1600.00</p>					

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	121.0	N/A	Grade Break?	N/A
Yes	Ramp Width (in)	65.0	N/A	Grade Break Slope (%)	0.0
Yes	Ramp Slope (%)	5.1	N/A	Grade Break XSlope (%)	0.0
No	Ramp XSlope (%)	2.5			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No		Road Slope (%)	0.9
	X Walk 1 Direction	To E		Road X Slope (%)	1.5
	X Walk 1 Width (in)	N/A		Clear Space?	N/A
	X Walk 1 Slope (%)	0.9	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	1.5	N/A	Storm Grate/Utility Hazard?	N/A
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
N/A	Any Obstructions?	N/A			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	10.1

