

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 50636Main Street:BLUE\_GROVE\_RDCross Street:RED\_WATER\_RDLocation:NEADA ID: 285FFFE00E5ARamp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:10

**Codes/Mitigation Info/Possible Solution** 



Street 1 Name	BLUE GROVE RD
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:	Co
Remove & Replace Entire Ramp.	
	No
	N/
	N/
	N/
	N/
Surveyor Notes:	N/
N/A	N/
	N/
	N/
	N/
PROW/ADA:	N/
Not Found, R304.5.1, R304.5.3	N/
	N/
	N/
	N/

LUE GROVE PROPERTY OF THE PROP	



Total Cost:



1850.00

Field Measurements/Component Compliance								
Compl	iance Description	Data	Comp	oliance	Description	Data		
N/A	Ramp Length (in)	46.0	Yes	Ramp	Slope (%)	8.2		
No	Ramp Width (in)	45.5	No	Ramp	XSlope (%)	2.6		
N/A	Flare Type LT	N/A	N/A	N/A Flare Type RT		N/A		
N/A	Flare Slope LT (%)	N/A	N/A	N/A Flare Slope RT (%)		N/A		
N/A	Flare Traversable LT?	N/A	N/A	N/A Flare Traversable RT?		N/A		
N/A	Landing Length (in)	N/A	N/A	N/A DWS Provided?		N/A		
N/A	Landing Width (in)	N/A	N/A	N/A DWS Contrast?		N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutte	Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	N/A		
	X Walk 1 Direction	To NW		X Wal	k 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Wal	k 2 Width (in)	N/A		
	X Walk 1 Slope (%)	1.6		X Wal	k 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	3.0		X Wal	k 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm	Grate/Utility Type			
		N/A				N/A		
			Yes	Surfac	ce Condition? (G/P)	Good		