## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9942	Main Street: ANDRILL_TR			Street:	PATTON_AV	Location:	SW		
ADA ID: 28786AEB53BD	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No					
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:				· · · ·					
	1 Designed								Data
and the local	A March	Remove & Replace Entire Ram	ip.	N/A	Ramp Length (in)	72.0	Yes	Ramp Slope (%)	7.6
	1			No	Ramp Width (in)	46.5		Ramp XSlope (%)	5.8
1 1 1 1 1 1	Allow and the			N/A	Flare Type LT	N/A		Flare Type RT	N/A
	AP is			N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
DAUTON A	TREE			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
AV & B	a subscription			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	2 Salar 17	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	Mr. Carle	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
and the second s	No the Martin			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
and the second of the	Silve and Ville			N/A	Shared Landing?	N/A			
	2014	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.5.3	6	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A CALL SE		,,,,,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
the the second s					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	PATTON AV	_			X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00	11/17	Obstruction Type	N/A		Storm Grate/Utility Type	17/5
			1000.00		Obstruction Type	N1/A		Storm Grate/Otimity Type	N//A
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

