

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 20419 Main Street: PARK_SOUTH_DR Cross Street: ROYAL_CREST_DR Location: SW ADA ID: 28A0B91EF793 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 13.75

Codes/Mitigation Info/Possible Solution



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1

PARK SOUTH DR None **ROYAL CREST DR** StopSign

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: R304.2.2, R304.5.3

Total Cost: 3200.00

Field Measurements/Component Compliance							
	Compliance Description		Data	Compliance Description		Data	
	N/A	Ramp Length (in)	48.0	No	Ramp	Slope (%)	9.1
	Yes	Ramp Width (in)	63.0	No	Ramp	XSlope (%)	3.1
	N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutte	Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	No
		X Walk 1 Direction	To SE		X Wal	k 2 Direction	To NE
	N/A	X Walk 1 Width (in)	N/A	N/A	X Wal	k 2 Width (in)	N/A
		X Walk 1 Slope (%)	3.8		X Wal	k 2 Slope (%)	5.6
		X Walk 1 X Slope (%)	4.0		X Wal	k 2 X Slope (%)	1.0
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
		Road Slope (%)	0.9	N/A	Clear	Space?	N/A
		Road X Slope (%)	3.5	N/A	Clear	Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
		Obstruction Type			Storm	Grate/Utility Type	
			N/A				N/A
				Yes	Surfac	ce Condition? (G/P)	Good
in	C.	and the same					





