cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30558 Mai	Main Street: GREENCREEK_DR		reet:	WANDERING_BROOM	Location:	Ν			
ADA ID: 28C95A385DCC Ran	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance: N				Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:						Compliance Description Data		
	Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	47.5	Yes	Ramp Slope (%)	5.3	
	Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.6	
		I	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A				
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	R304.5.3	1	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
6 <u>6</u>			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
h h			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name WANDERING BROOK DR				X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	2.3	
Stop Condition-Street 2 Stop	Sign			X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	4.5	
Street 2 Name GREENCREEK	DR		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	one			Road Slope (%)	6.1	N/A	Clear Space?	N/A	
				Road X Slope (%)	3.1	N/A	Clear Space to XWalk (in)	N/A	
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A	

Yes Surface Condition? (G/P)

Good

