

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18705 Main Street: HAVEL_CT Cross Street: KIRKPATRICK_RD Location: E

ADA ID: 2906DE2B496D Ramp Type: Perp Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name HAVEL CT
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

| Possible Solutions: | Co |
|-------------------------------|-----|
| Remove & Replace Entire Ramp. | N/A |
| · | Yes |
| | N/A |
| | N/A |
| | N/A |
| | Yes |
| Surveyor Notes: | Yes |
| N/A | Yes |
| | Yes |
| | N/A |
| | N/A |
| PROW/ADA: | Yes |
| Not Found, R305 | Yes |
| | N/A |
| | N/A |
| | N/A |

| Total Cost: | \$ 1850.00 |
|-------------|---------------|

| Field Measurements/Component Compilance | | | | | | | |
|---|-----|-----------------------|-------|---------------------|-----------------------------|------|--|
| Compliance Description | | Data | Comp | oliance Description | Data | | |
| | N/A | Ramp Length (in) | 43.0 | Yes | Ramp Slope (%) | 7.4 | |
| | Yes | Ramp Width (in) | 48.0 | Yes | Ramp XSlope (%) | 1.2 | |
| ı | N/A | Flare Type LT | None | N/A | Flare Type RT | N/A | |
| | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| | Yes | Landing Length (in) | 51.0 | No | DWS Provided? | No | |
| | Yes | Landing Width (in) | 48.0 | N/A | DWS Contrast? | No | |
| | Yes | Landing Slope (%) | 0.8 | N/A | DWS Length (in) | N/A | |
| | Yes | Landing X Slope (%) | 1.2 | N/A | DWS Full Width? | No | |
| | N/A | Landing Curb? (Y/N) | No | N/A | DWS Offset (in) | N/A | |
| | N/A | Shared Landing? | No | | | | |
| | Yes | Gutter Ponding? | No | Yes | Gutter Slope (%) | 4.5 | |
| , | Yes | Gutter Lip Ht (in) | 0.0 | Yes | Gutter X Slope (%) | 1.6 | |
| | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A | |
| | | X Walk 1 Direction | To NW | | X Walk 2 Direction | N/A | |
| | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | |
| | | X Walk 1 Slope (%) | 1.7 | | X Walk 2 Slope (%) | N/A | |
| | | X Walk 1 X Slope (%) | 0.7 | | X Walk 2 X Slope (%) | N/A | |
| | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| | | Road Slope (%) | N/A | N/A | Clear Space? | Yes | |
| | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A | |
| | Yes | Any Obstructions? | No | Yes | Storm Grate/Utility Hazard? | No | |
| | | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | | N/A | | | N/A | |
| | | | | Yes | Surface Condition? (G/P) | Good | |
| | | | | | | | |





