

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23302	Main Str	Main Street: COLONY_RD			MORROWICK_RD	Location:	SW		
ADA ID: 294562AB625B		Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				
Co		Field Measurements/Component Compliance							
		Possible Solutions:		Compliance Description		Data Compliance Description			Data
		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	Vith	N/A	Ramp Length (in)	65.0	No	Ramp Slope (%)	11.1
				No	Ramp Width (in)	42.0	No	Ramp XSlope (%)	4.7
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
d.				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Control Contro				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
de la companya de la comp		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
and the second				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Part Harris	S VIII			N/A	Shared Landing?	N/A			
10 IS A PA	B Like	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	EVI	R304.5.1, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
CA A. I	·····,····,····,·····,·····,····		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes	
A CONTRACTOR	2.2.11				X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
	A STRACT			N/A	X Walk 1 Width (in)	113.0	N/A	X Walk 2 Width (in)	109.0
Street 1 Name	COLONY RD	-			X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	3.5
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	4.2		X Walk 2 X Slope (%)	0.5
Street 2 Name	MORROWICK RD			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes
Stop Condition-Street 1	Signal				Road Slope (%)	4.2	N/A	Clear Space?	N/A
	-				Road X Slope (%)	0.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good