

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 44732Main Street: WRENFIELD_CTCross Street: ALEXA_RDLocation:SWADA ID: 2972F28845E6Ramp Type: BlendTrans2Initial Pass/Fail: PassOverall Compliance: NoSeverity Score:10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

WRENFIELD CT StopSign ALEXA RD None Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:
N/A

PROW/ADA:
Not Found, R305

Total Cost: \$ 3200.00

9	Compliance Description		Data	Data Compliance Description		Data
ı	N/A	Ramp Length (in)	101.5	Yes	BlendTrans Slope (%)	3.9
,	Yes	Ramp Width (in)	54.0	Yes	BlendTrans XSlope (%)	0.2
ı	N/A	Flare Type LT	None	N/A	Flare Type RT	None
ı	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
ı	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
ı	N/A	Landing Length (in)	N/A	No	DWS Provided?	No
ı	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	No
ı	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
ı	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	No
ı	N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
ı	N/A	Shared Landing?	No			
,	Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.4
١	es/	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.5
ı	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To E		X Walk 2 Direction	To N
		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	2.5		X Walk 2 Slope (%)	5.7
		X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	4.1
ı	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	0.4		Clear Space?	Yes
		Road X Slope (%)	2.8	N/A	Clear Space to XWalk (in)	N/A
,	Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Obstruction Type			Storm Grate/Utility Type	
			N/A	l		N/A
				Yes	Surface Condition? (G/P)	Good

No

Curb Slope (%)

10.6





