cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10038802 Main Street: STEELE_CREEK_RD Cross Street: N/A Location: SW									
Intersection ID: 10038802 Main Street: STEELE_CREEK_RD		Cross	Street:	N/A	Location:	SW			
ADA ID: 298348221B3F Ramp Type: PerpDiag			Initial I	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	46.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data Com			Comp	liance Description	Data
BILL E		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	95.0	No	Ramp Slope (%)	8.7
71111		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	7.9
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
1 .				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
the second				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
11111		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the state of the s		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Ct -				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Pr. 1				N/A	Shared Landing?	N/A			
Contraction of the second		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Ten March	R304.5.1, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	24			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	Yes
	A State of States				X Walk 1 Direction	To E		X Walk 2 Direction	To N
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	112.0
Street 1 Name	STEELE CREEK RD	-			X Walk 1 Slope (%)	4.2		X Walk 2 Slope (%)	1.1
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.5		X Walk 2 X Slope (%)	6.2
Street 2 Name	ENTRANCE			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	Yes
Stop Condition-Street 1	StopSign				Road Slope (%)	5.9	N/A	Clear Space?	N/A
,					Road X Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
		······ •···· •				N/A			N/A
						10/1			

Yes Surface Condition? (G/P)

Good

